


BIKE	Honda CRF1000L Africa Twin	PART NO.	RHA - 173
YEAR	2015 - Current	FIT KITS	Z039.10579
NOTES	Where not supplied use original fittings.	FEATURES	DB KILLER Z038.10050 (W)



- |  |   |
|--|---|
| 1 Serket Silencer 400mm RSC366               | 8 Silencer Mounting Bracket (Z015.31287)    |
| 2 3 x M8 x 25mm Cap Head Bolt (Z017.10073)   | 9 Heat Shield Mounting Bracket(Z015.31289)  |
| 3 2 x M8 x 17mm Washer (Z017.10831)          | 10 25mm Rubber Washer (Z017.12779)          |
| 4 2 x M8 x 5mm Alloy Spacer (Z026.20049)     | 11 Black Composite Heat Shield (Z028.20325) |
| 5 Alloy Bolt Finisher (Z026.20068)           | 12 4 x Black Fibre Washer (Z017.12781)      |
| 6 2 x M6 x 12mm Button Head Bolt(Z017.10620) |   |
| 7 47-51mm Clamp (Z016.10003)                 |   |

E-MARK	e11 00517
ISSUE NO.	03
DATE	18/11/16
AUTHORISED	M.Ydlibi
CHECKED	

**NOTE:** ENSURE SCORPION SYSTEM IS CLEAR OF MOVING PARTS AND ALL ORIGINAL FUNCTIONS WORK CORRECTLY.



A) Remove original exhaust from bike, taking care to keep all original components in a safe place.

B) Refit Scorpion exhaust as per line diagram above. Ensure that the heat shield if fitted last.

C) When fitted take bike for a short ride to ensure all functions are correct.

D) When bike & exhaust are cool enough check all nuts and bolts are still secure.

Cleaning instruction overleaf:

Box: PLOCK 2

BIKE	Honda CRF1000L Africa Twin	PART NO.	RHA - 173
YEAR	2015 - Current	FIT KITS	Z039.10579
NOTES	Where not supplied use original fittings	FEATURES	DB KILLER Z038.10050 (W)

Thank you for purchasing your Scorpion Silencer.

Care of your exhaust: Please refrain from cleaning silencer with heavy solvents or abrasives!

Vielen Dank für den Kauf eines Scorpion Schalldämpfers! Pflegehinweis: Bitte verwenden Sie niemals Scheuermittel oder aggressive Reiniger zur Pflege Ihres Auspuffes!

Merci d'avoir choisi un échappement Scorpion.

Entretien de votre silencieux: Ne pas utiliser de solvants ou de produits abrasifs!

"Muchas gracias por adquirir un Silencioso Scorpion. Le recomendamos no limpiar el silencioso con productos abrasivos o aquellos que contengan disolventes."